

Photo Log

Stony Ford Road – Ford Farms

by Andreescu, Stephanie



P9220001 – Upstream of Disturbance, Looking Upstream



P9220002 – Upstream of Disturbance, Looking Downstream




P9220003 – Upstream of Disturbance, Looking at Bank



P9220004 – Upstream of Disturbance, Sediment



P9220005 – Upstream of Disturbance, Sediment



P9220006 – Upstream of Disturbance, 2 Caddisfly cases attached to bottom of rock



P9220007 – Upstream of Disturbance, Looking at Fill



P9220008 - Upstream of Disturbance, Looking at Fill



P9220009 – Taken Near Fill Looking Upstream



P9220010 – Relocated Stream Channel, Looking Upstream



P9220011 – Relocated Channel, Looking Downstream



P9220012 – Relocated Channel, Looking Downstream



P9220013 – Relocated Channel, Looking Upstream



P9220014 – Wetland Area, Documentation of Standing Water, Cattails



P9220015 – C&D Material Placed in Wetland, Facing West



P9220016 – C&D Material Placed in Wetland, Facing East



P9220017 – C&D Material Placed in Wetland



P9220018 – C&D Material Placed in Wetland



P9220019 – C&D Material Placed in Wetland, Looking Northwest



P9220020 – C&D Material Placed in Wetland, Soft Rush



P9220021 – C&D Material Placed in Wetland



P9220022 – Relocated Stream, C&D Material Forming Right Descending Bank



P9220023 – Compromised Silt Fence Along Relocated Stream, SE Border of Property



P9220024 – Silt Fence Along Relocated Stream, SE Border of Property



P9220025 – Narrowed Stream Leaving Site



P9220026 – Downstream of Site, Looking Upstream



P9220027 – Downstream of Site, Looking Downstream



P9220028 – Potential Wetland Fill